BRANNER SURVEYING

MEMBER-PROFESSIONAL LAND SURVEYORS OF OHIO

PEACH RIDGE ROAD ROUTE 3 BOX 240B ATHENS, OHIO 45701

JOHN M. BRANNER Registered Land Surveyor

TELEPHONE (614) 592-5778

DESCRIPTION OF A 0.52 ACRE TRACT

Situated in Farm-lot 3 and Farm-lot-6 of Section 12, T.8, R.14, Alexander Township, Athens County, Ohio and being more particularly described as follows:

Commencing at the South-west corner of a 24.00 acre tract as recorded in Volume 18, Page 403, Athens County Deed Records, said point marked by a stone at the North-west corner of Farm-lot #3 and the North-east corner of Farm-lot#2, thence, South 83 Degrees 45 Minutes East, 808.3 feet to a point; thence, North 06 Degrees 15 Minutes East, 116.5 feet to an iron pin at the Northwest corner of a 0.83 acre tract as recorded in Volume 303, Page 179; thence, South 07 Degrees 20 Minutes East, 107.9 feet to an iron pin at the South-west corner of said 0.83 acre tract, said point being the point of beginning for the tract of land herein described:

Thence, along the South-line of 0.83 acre tract, South 85 Degrees 40 Minutes East, 318.8 feet to a point in County Road 21 , passing an iron pin at 258.8 feet; thence, along said road , South 21 Degrees 49 Minutes 24 Seconds East, 66.55 feet to a point; thence, leaving said road and along a fence-line, North 88 Degrees 52 Minutes West, 332.49 feet to an iron pin, passing an iron pin at 50.0 feet; thence, North 07 Degrees 20 Minutes West, 79.95 feet to the point of beginning and containing 0.52 acres, of which 0.12 acres are in Farm-lot 6 and 0.40 acres are in Farmlot 3.

Subject to all easements and rights of way of record.


The above description is based on existing deed descriptions prepared from a survey by R.C. Glascow Registered Land Surveyor.

pasamption checked for

John M. Branner Registered Land Surveyor 6805

Hotheractical Accuracy

rect /2





and the state of t

| ALLEN DESCRIP | TION CHECK-11: | :19:2401/09/91 | |
|----------------------|-----------------|----------------|-----------------|
| " | | 40 MIN | O SEC |
| MM | | | |
| 1 | 90 DEG | O MIN | O SEC |
| SD- 318.8 | V.A 90 | HD- 318 8 FT | |
| 2 | 7 DEG | 20 MIN | O SEC |
| 8E | | | |
| 2 | 90 DEG | () M I N | O SEC |
| SD- 79.95 | V.A 90 | HD- 79.95 FT | |
| (3) | 88 DEG | 52 MIN | o sec |
| SE | | | |
| .23 | 90 OEG | O MIN | O SEC |
| SD- 332.49 | V.A 90 | HO- 382.49 FT | |
| 4 | 29 OEG | 49 MIN | 24 SEC |
| MM | | | |
| 4 | 90 DEG | O MIN | o sec |
| SD- 66.55 | V.A 90 | MD- 66.55 FT | |
| +0.\$686434B8E+08 | | | |
| 1.85A450762E-03 | | | |
| ٥ | 5000 | 5000 | |
| 7 | 5024.0881623593 | | 4682.1113398655 |
| 2 | 4944,7921252528 | | 4692.3162892991 |
| 3 | 4938.2157695268 | | 5024.7412457103 |
| 4 | 4999.9964313566 | | 5000.0015544508 |
| 52038930414382 ACRES | | | |