

PROPERTY LOCATION:

Situated in the Township of Trimble, County of Athens, State of Ohio, and being a part of Fraction 3, Township 11N, Range 14W, of the Ohio Company's Purchase.

Being a Survey of a parcel conveyed to Patricia McNally, as recorded in O.R. Volume 387, Page 875, in the Athens County Deed Records, and being all of Auditor's P.P.N. M01-00100133-00.

Bearings of this plat are based on the centerline of Brick Plant Road, as being S 79°00'00" E, and is an assumed Meridian used to denote angles only.

LEGEND

- - 3/4" o.d. Iron Pipe Found
- - 2" o.d. Iron Pipe Found
- - Iron Pin Set
- 5/8" Rebar with a Red I.D. Cap Labeled S.A. England #7452
- ⊙ - 12" o.d. Corner Post

PREPARED BY:

S.A. ENGLAND & ASSOCIATES
 Professional Land Surveying
 P.O. Box 1770, 5179 Walnut Road
 Buckeye Lake, Ohio 43008
 740-928-8680 FAX 740-928-9565
 WWW.SURVEYOHIO.COM

I hereby certify that an actual survey was made of the premises, and that this plat is correct to the best of my knowledge.

Signature
 Date Scott A. England, P.S.
 Ohio Registered Surveyor #S-7452

PREPARED FOR:

Patricia McNally
 10766 Congress Run Rd.
 Gloucester, Ohio

Plat of Survey

Trimble Twp., Athens Co., State of Ohio, part
 Frac. 3, Twp. 11N, Rng.14W, Ohio Company's Purchase.

POINT OF BEGINNING:
 Intersection of centerlines of
 Congress Run Road & Brick Plant Rd.;
 bears South 2881.39 feet & West
 1358.29 feet from NE Corner Fraction 3

